


PANGO® WRAP		
OVERLAP WITH PANGO® TAPE		
CONCEPTUAL FIELD ILLUSTRATION		
PAGE 1 OF 2	NOT TO SCALE	28 AUGUST 2017

Conceptual Field Illustrations are drawings prepared by Stego® Industries, LLC and intended to illustrate potential installation or repair details. These illustrations are not design documents and must be reviewed and approved by the appropriate design professional prior to utilization. Likewise, in no way do these illustrations waive the requirements of the Contract Documents or supersede local code requirements. A Conceptual Field Illustration that does not comply with the applicable version of ASTM E1643 and Pango® Wrap's installation instructions, by definition, is not a Stego recommendation; rather, it is merely an example of a potential way to complete the work.



PANGO® WRAP

REPAIR OF DAMAGED AREA WITH PANGO® TAPE

CONCEPTUAL FIELD ILLUSTRATION

PAGE 2 OF 2

NOT TO SCALE

28 AUGUST 2017

Conceptual Field Illustrations are drawings prepared by Stego® Industries, LLC and intended to illustrate potential installation or repair details. These illustrations are not design documents and must be reviewed and approved by the appropriate design professional prior to utilization. Likewise, in no way do these illustrations waive the requirements of the Contract Documents or supersede local code requirements. A Conceptual Field Illustration that does not comply with the applicable version of ASTM E1643 and Pango® Wrap's installation instructions, by definition, is not a Stego recommendation; rather, it is merely an example of a potential way to complete the work.